

CASE NUMBER../ MC00000253 INV INIT/ PORT/ KODD LAST UPDATE/ 06MAR01
CASUALTY TYPE: VESSEL/ X PERSONNEL/ FACILITY/ POLLUTION/ MARPOL/
INCIDENT DATE/ 05JAN00 TIME/ 1502 KNOWN/ X ESTIMATED/ REF CASE/
NOTIFY DATE../ 05JAN00 TIME/ 1535 REPORTER TYPE/ USCG
SUBJECT...../ KODD/RADUGA/SINKING/JONES LOCAL FILE REFERENCE/
LOCATION...../ CHINIAK, ALASKA LOCAL CODE/
INCIDENT STATUS: VERIFIED/ X NOT VERIFIED/ VERIFIED, NOT REPORTABLE/
NOTIFY/ ACTION: CTF/ RETURN/ (TO IAPR)

--- VALIDATION AND ENDORSEMENT ---

	END/FWD	END/CLS	RETURN	USER-ID	NAME	DATE
INVESTIGATOR:	X				LT	09MAR00
UNIT COMMAND:	X				LT	09MAR00
DIST REQ?	:					
HQ REQ? Y :		X				06MAR01

--- GENERAL INFORMATION ---

CITY/ CHINIAK ST/ AK WATERBODY/ NORTH PACIFIC OCEAN COASTAL
RIVER MILE/ LATITUDE/ N 57-29.9 LONGITUDE/ W 152-10.9
CAS SUMMARY:TYPE/ SINKING CLASS/ NONE
POSSIBLE DRUG INVOLVEMENT?/ N PUBLIC VESSEL/ BOATING/
DEATHS/ MISSING/ INJURED/ TOTAL DAMAGE/ 65000
ENV IMPACT: MODE/ SEVERITY CATEGORY/ MATERIAL CATEGORY/
OSC/ EPA REGION/ CLEANUP REQ?/
RESPONSE BY NSF?/ NSF TIME TO RESPOND/ HOURS
NOTIFICATION FROM NRC?../ NRC CASE../
NOTIFICATION FROM APHIS?/ N APHIS PORT/

--- INCIDENT BRIEF ---

F/V RADUGA BEGAN TAKING ON WATER AFT AND SANK AFTER COMING DOWN HARD FROM A WAVE AND HEARING A CRACK. THE VSL SLOWLY SANK THEN ROLLED. 3 POB ABANDONED THE VSL. 2 PERS ENTERED THE RAFT, 1 PERS UNABLE TO REACH RAFT DUE TO WATER IN SURV SUIT. ALL WERE RESCUED BY A/S KODD H-60 & RTND TO KODIAK. THEY WERE TREATED & RELEASED FM LOCAL HOSPITAL SAME DAY FOR MILD HYPOTHERMIA.

--- ACTIONS REPORTED ---

SEL	CASE SUPPLEMENTS	SEL	EVENT SUPPLEMENTS
1	WITNESS LIST.....(IAWL)/ X	14	COLLISION OR GROUNDING.(MCCG)/ 0
2	COMDT RECOMMENDATION.(MCCR)/ X	15	EQUIP FAILURE.....(MCDR)/ 0
3	CASUALTY DETAILS.....(MCDD)/ X	16	FLOOD,CAPSIZE,SINKING..(MCFC)/ 1
4	NARRATIVE SUPPLEMENT.(MCNS)/ X	17	FIRE,EXPLOSION.....(MCFE)/ 0
5	PERS ACTION RECOMMEND(MCPA)/ 0	18	HUMAN FACTORS SUPP.....(MCHF)/ 0
6	POLLUTANT DETAILS....(MCPD)/ 0	19	HAZ MAT INVOLVEMENT....(MCHM)/ 0
7	MARPOL DETAIL SUP....(MCMD)/ 0	20	LIFESAVING SUPPLEMENT..(MCLS)/ 1
8	OPERATIONAL CONTROLS (PSOC)/ 0	21	PERSONNEL CASUALTY.....(MCPC)/ 0
9	PERSONNEL INVOLVEMENT(MCPI)/ 0	22	STRUCTURAL FAILURE.....(MCSF)/ 0
10	SMI SUPPLEMENT.....(MCSI)/ 0		
11	TOWING SUPPLEMENT....(MCTS)/ 0		
12	SUBJECT SUPPLEMENT... (MCSS)/		
13	WEATHER FACTORS.....(MCWX)/ X		

-SUPPLEMENTS-

VESSLS INVOLVED/ 1	FLAG	SERVICE	P M F P P S TOW
VIN	NAME	US FISHING BOAT	D D R A I I REF DMG
D605456	RADUGA		TOTL
ENF ACTIONS: REQ LOU/	REQ SURETY BOND/	NONE/ X	
(ENTER HERE IF ASSOCIATED WITH AN MC CASE, OTHERWISE RECORD IN PSAR)			

FACILITIES INVOLVED/ 0

--- INVESTIGATION RESOURCES UTILIZED ---

CASE NUMBER/ MC00000253

UNIT/ KODD

--- RECOMMENDATION ---

1. BRIEF/ CHANGE ELLIOT SER # STENCILS ACTION PORT/ GMMI
RECOMMEND COMDT DISCUSS USE OF MORE PERMANENT MARKING ON ELLIOT/ISSI RAFTS
TO ENSURE IT DOES NOT QUICKLY WEAR OFF. HAMPERED THIS INVESTIGATION AS IT
SLOWED TIME TO IDENTIFY RAFT AND MANUFACTURER.

--- UNIT ENDORSEMENT ---

ENDORSEMENT COMPLETE/ X STATUS/ RECOMMENDED LAST UPDATE/ 09MAR00
Support recommendation of IO.

--- HEADQUARTERS ENDORSEMENT ---

ENDORSEMENT COMPLETE/ X STATUS/ COMPLETE LAST UPDATE/ 06MAR01
We concur with the intent of this recommendation. Having markings on the
ELLIOT/ISSI liferaft that were more permanent and better able to withstand
the elements would have improved the ability to quickly identify that raft
and its manufacturer during this investigation. However, while it may have
been slowed by the condition of the markings, the investigator was able to
ultimately identify the liferaft in this case. In addition, there is no
evidence that the lack of more permanent markings on the liferaft
negatively impacted its maintenance, inspection or use before or during the
casualty. Therefore, we do not find any compelling need to amend the
current regulations in 46 CFR 151-33 regarding the required markings for
liferafts. However, this issue will be publicized on the Office of
Compliance's commercial fishing vessel safety intranet web site and we will
forward a copy of this investigation case to each District Fishing Vessel
Safety Coordinator.

W. D. Rabe
By direction

CASE NUMBER/ MC00000253

UNIT/ KODD

--- RECOMMENDATION ---

2. BRIEF/ LABEL BAILERS IN ALL RAFTS ACTION PORT/ GMMI
RECOMMEND COMDT CONSIDER REQUIRING RAFT MANUFACTURERS TO LABEL EQUIPMENT
THAT MIGHT NOT BE READILY IDENTIFIABLE. MANY BAILERS APPROVED TODAY ARE
NOT, IN OUR OPINION, READILY IDENTIFIABLE AS BAILERS. IN THIS CASE, THEY
WERE LIKELY IN THE RAFT BUT MISTAKEN TO BE SOME OTHER SORT OF CONTAINER.
LABELING WOULD AID THOSE ALREADY IN DEMANDING, CRISES THINKING SITUATIONS.

--- UNIT ENDORSEMENT ---

ENDORSEMENT COMPLETE/ X STATUS/ RECOMMENDED LAST UPDATE/ 09MAR00
Support IO's recommendation. With manufactures reducing size of gear
inorder to fit easier into liferaft canisters some gear is no longer
familiar to vessel operators. This recommendation would greatly assist
personnel in identifying emergency gear.

--- HEADQUARTERS ENDORSEMENT ---

ENDORSEMENT COMPLETE/ X STATUS/ COMPLETE LAST UPDATE/ 05MAR01
We do not concur with this recommendation. The evidence does not indicate
whether the crew was unable to locate the bailer because they could not
identify it, didn't know where it was located, or because it was missing.
Even so, we believe that operators and crewmembers of vessels have a
responsibility to ensure they are familiar with the identification,
location and use of lifesaving equipment carried on the vessels on which
they are employed.

W. D. Rabe
By direction

CASE/ MC00000253 PORT/ KODD SUBJECT/ KODD/RADUGA/SINKING/JONES DATE/ 05JAN00

--- COMMENTS ---

On 05JAN00, the F/V RADUGA was enroute Kodiak from near Chiniak, Alaska with a load of 10,000-12,000 pounds of cod. The fiberglass, 40 foot fishing vessel was being driven through 12-17 foot waves in limited visibility at a speed of approx 6 knots. The master later reported as he came off of the crest of waves he would slow the engine to glide down the wave. As he came over a wave, he noted he backed down yet came down unusually hard. He also heard a loud crack. The vessel reportedly plowed through the next wave as the master noted she began feeling sluggish aft. He looked aft and noted the aft deck was half underwater. The two other crewmembers, who had been asleep in the cabin due to the rough sea state, were summoned and began preparing for abandon ship. The master made a distress call to A/S Kodiak and steered the vessel into the seas to maintain stability. The crew launched the liferaft and donned survival suits. Over approx 15 minutes, the vessel took on more and more water and began listing. Finally, the vessel was stopped as the liferaft broke the weak link and the engine died. As the vessel lay on her side, the crew abandon the vessel into the inflated liferaft. One crewmember was unable to reach the liferaft due to water in his suit. An A/S Kodiak C-130 arrived and flew cover topside as an H-60 arrived and hoisted the crew to safety. The crew was flown to Kodiak where they were treated and released for hypothermia at Providence Medical Center, Kodiak. They were then transported by LT to MSD Kodiak where interviews were conducted. Later that night, another fishing vessel belonging to the master's brother arrived in Kodiak with the EPIRB and the raft. LT viewed the raft at that time and requested that it be provided to MSD for further evaluation. A Notice to Mariners was published warning mariners to keep watch for the vessel. It was last seen floating by only one stern quarter. It is thought to have sunk as it was never found by two overflights conducted by A/S Kodiak in the following week after the incident.

Crew interviews determined the following:

1. The raft inflated fine; however, crewmembers could not locate a bailer to dewater the raft. The bailer was not found upon review by LT. It is unknown if the bailer was in the raft or not. It was determined that it was likely a new style small plastic bag rather than an older plastic bucket type apparatus. It is likely the bailer was onboard but crewmembers could not identify it. Further, the serial number had washed off due to water in the raft making manufacturer tracking difficult during the investigation. The raft is thought to be a 4 man, Elliot, serial number P162, lot 53, manufactured 12FEB98 and purchased through Ocean Safety Services, Homer, AK.
2. The survival suit reported to have leaked was tested and found satisfactory. It is suspected that it may have leaked slightly from foot valves, as many do. Most likely, more water came from the suit being too large for the individual in it or partially unzipped. It is to be returned to the owner with caution to have serviced/tested further before use.
3. Recent work had been done on the vessel in drydock in Dec 1999. The shaft had been replaced with questionable change from a 2 inch to a 2.25 inch shaft and possible removal of the bearing. The keel coolers had also been opened in the yard; were reported working sat. It was reported fiberglassed back in. Additional aft cabin work had been done on the temporary aft cabin structure with a midship portion being completed just before this trip. It was reported that no hull breaching was done for such installation. Bilge pumps, located in

CASE/ MC00000253 PORT/ KODD SUBJECT/ KODD/RADUGA/SINKING/JONES DATE/ 05JAN00

--- COMMENTS ---

lazerette, fish hold and 2 in the engine room were reported by master as working sat and coming on approx every 30 minutes. One crewmember reported that one bilge pump had problems and was repaired in Kodiak. He further stated they had been watching it on this trip and it had been fine.

4. It was reported that the vessel had relatively small scupper openings. Similar vessels have been viewed and it is noted that the scuppers are small and, sometimes, few and far between. This is not thought to have caused the incident; however, may have led the vessel to retain more water and consequently capsize quicker. The added cabin aft for baiting also likely increased water retention.

Final analysis of the case has found no definitive cause of this incident. The crack heard appears to have been a loud, distinct indicator along with the immediate sluggishness of the vessel. It is thought that a catastrophic failure of some sort occurred either to the hull itself or a major through hull fitting. This obviously leads to some suspicion of the shaft work, which was not checked by a surveyor. However, the vessel continued driving into the seas indicating the systems were still operational at least. Only solid decisions able to be made are from that gear which was recovered; the liferaft. Two recommendations based on inspection of raft, crew discussion and phone conversation with raft manufacturer.

1. Recommend ISSI/Elliott review the ink labeling process they utilize and implement a system of more permanent marking. The U.S. information portion of the label was unreadable due to water and wear after only a few hours exposure.
2. Recommend that COMDT evaluate possibility of requiring all raft manufacturers clearly label equipment that might not be readily identifiable to some users. In this case, the bailers were not identified. Either they were not placed in the raft at manufacturer plant (had not yet been serviced due to age) or were not identified by the crew. They are small plastic bag looking items which would not appear to be the main bailers even to this inspector had I not had several years raft inspection experience. Recommend they be labeled.

Did not list pers casualty of mild hypothermia in MCDD based on all members being treated and released same evening from hospital. Drug testing not completed due to limited value of vessel/property damage.

Operator reports he has been leasing the vessel for some time; he was unable to contact owner to date. Case complete. Raft and survival suit at MSD Kodiak to be given back to operator.

LT